

DCA09FR008
Lake Buena Vista, Florida
July 5, 2009

Epcot Beam
Maintenance Record
1/6/09 – 7/2/09

WO Number	Initial Report Date	Location of Work	Description of Work	WO Status	WO Status Date	Work Type	LWOI Priority	Craft Assigned	Labor Start Date	Labor Finish Date	WO Equip Desc	Equip Type	Problem	Remedy	Long Description
1 22273541	01/06/09	NS Monorail Shop	mapo at 185	COMP	01/06/09	PC	4		01/06/09	01/06/09	AMVS EPCOT Monorail Beam	BEAM			REPLACED TRANSMITTER AND POWER SUPPLY. WET FROM SPRINKLER
2 28621731	12/17/08	NS Monorail Shop	M/RM MONO EPCOT MAPO System	COMP	01/15/09	PM	5	MECH/TRAN	01/14/09	01/16/09	AMVS EPCOT Monorail Beam	BEAM			9/27/04 TGE- Added annual per Doug D & Jason K.
3 22361404	01/15/09	NS Monorail Shop	EPCOT CENTER BEAM, AMBERS 155-TO-185	COMP	01/15/09	PC	2		01/15/09	01/15/09	AMVS EPCOT Monorail Beam	BEAM			FOUND THE TRANS AT 186 HAD NO OUTPUT. REFUSED AND RESET THE TRANS...10-8 SJF
4 22371483	01/16/09	NS Monorail Shop	MAPO problems at pylon 186. Trains holding at 165 with amber.	COMP	01/16/09	UCL	3		01/16/09	01/16/09	AMVS EPCOT Monorail Beam	BEAM			Checked output voltage and frequency, ok. Problem corrected itself. rc
5 22396737	01/18/09	NS Monorail Shop	mapo at 185	COMP	01/18/09	PC	4		01/18/09	01/18/09	AMVS EPCOT Monorail Beam	BEAM			REPLACED TRANSMITTER AND POWER SUPPLY. WET FROM SPRINKLER
6 22406422	01/19/09	NS Monorail Shop	mapo transmitter 186 epcot	COMP	01/19/09	PC	3		01/19/09	01/19/09	AMVS EPCOT Monorail Beam	BEAM			install baffle to stop sprinkler damage
7 22425065	01/21/09	NS Monorail Shop	EPCOT - mapo problems - receiving amber at 155 clearing 185	COMP	01/21/09	UCH	3		01/21/09	01/21/09	AMVS EPCOT Monorail Beam	BEAM			replaced power supply at pylon 186... 10-8 att.
8 22490558	01/27/09	NS Monorail Shop	EPCOT BEAM MAPO transmitter at pylon 10 is 10-7. Replaced 2amp and 1amp fuses.	COMP	01/27/09	UCL	3		01/27/09	01/27/09	AMVS EPCOT Monorail Beam	BEAM			
9 22496132	01/27/09	NS Monorail Shop	EPCOT BEAM. Replace reflectors at 14, 204, 285, 379, 225. Reflective tape at 385 and 195.	COMP	01/29/09	PC	3		01/27/09	01/28/09	AMVS EPCOT Monorail Beam	BEAM			
10 22574434	02/04/09	NS Monorail Shop	EPCOT. LU. 1-2-3 ASSIST HAINES CITY FIRE EXT. TO RECERT.	COMP	02/04/09	PC	2		02/04/09	02/04/09	AMVS EPCOT Monorail Beam	BEAM			
11 22576697	02/05/09	NS Monorail Shop	EPCOT - INSTALL SPACER PLATE BEHIND TRANSPONDER AT PYLON 363	COMP	02/05/09	PC	1		02/05/09	02/05/09	AMVS EPCOT Monorail Beam	BEAM			
12 22711311	02/16/09	NS Monorail Shop	EPCOT BEAM BENCH REPAIR AND TEST MAPO POWER SUPPLIES	COMP	03/02/09	PC			02/16/09	02/24/09	AMVS EPCOT Monorail Beam	BEAM			
13 22746669	02/19/09	NS Monorail Shop	EPCOT MAPO ISSUES - Trains receiving mapo problems at various places around beam.	COMP	02/19/09	UCH	4		02/19/09	02/22/09	AMVS EPCOT Monorail Beam	BEAM			REPLACED TX AT 165, 175, 204 AND 212. REPLACED P/S AT PYLONS 204, 212 AND 175. EPCOT LOOP IS 10-8 AT THIS TIME. DRS. BASOY 2-22-2009
14 22749343	02/19/09	NS Monorail Shop	EPCOT FALSE AMBERS AT 355 CLEARING AT 371	COMP	03/02/09	UCL	2		02/19/09	02/19/09	AMVS EPCOT Monorail Beam	BEAM			BENCH REPAIR TRANSMITTERS
15 22756033	02/20/09	NS Monorail Shop	EPCOT BEAM. AMBERS @345 TO 372, REPL. THE TRANS	COMP	02/20/09	PC	2		02/20/09	02/20/09	AMVS EPCOT Monorail Beam	BEAM			INTERMITTENT PROBLEM
16 22771982	02/21/09	NS Monorail Shop	Test/Repair MAPO power supplies removed from EPCOT beam.	COMP	02/21/09	PC	3		02/21/09	03/17/09	AMVS EPCOT Monorail Beam	BEAM			REPL THE TRANS AND TESTED 10-8 SJF
17 22780017	02/23/09	NS Monorail Shop	Make up 20 RG-6 Jumpers for PDMS.	COMP	03/02/09	SP	3		02/23/09	02/23/09	AMVS EPCOT Monorail Beam	BEAM			Tested all three power supplies and found one with blown fuse.
18 22786107	02/24/09	NS Monorail Shop	Install transponder at pylon 357	COMP	02/24/09	PC	2		02/24/09	02/24/09	AMVS EPCOT Monorail Beam	BEAM			Replaced fuse and tested 10-8. EDS01
19 22821822	02/26/09	NS Monorail Shop	TEST overcurrent relays for EPCOT rectifiers.	COMP	03/02/09	PC	3		02/26/09	02/26/09	AMVS EPCOT Monorail Beam	BEAM			
20 22822028	02/26/09	NS Monorail Shop	Install new transponder at pylon 357	COMP	02/27/09	PC	2		02/26/09	03/11/09	AMVS EPCOT Monorail Beam	BEAM			
21 23061516	03/20/09	NS Monorail Shop	INSTALL OLD TRANSPONDER AND SPACER BLOCK AT PYLON 357	COMP	03/21/09	PC	1		03/20/09	03/21/09	AMVS EPCOT Monorail Beam	BEAM			

39	25935885	06/16/09	NS Monorail Shop	EPCOT BEAM - MAPO- Trains Receiving Amber	COMP	06/16/09	PC	4			AMVS EPCOT Monorail Beam	BEAM	Trains receiving ambers between switch 9 and Pylon 25 and clearing at Pylon 45.
40	26032358	06/20/09	NS Monorail Shop	Epcot beam all trains false amber at pylon 20	COMP	06/21/09	PC	0	06/20/09		AMVS EPCOT Monorail Beam	BEAM	Checked power supply and transmitter at pylon 36. Transmitter intermittent. Replaced. green mbbs at pylon 45. Found bad transmitter at pylon 48.
41	26052245	06/21/09	NS Monorail Shop	Check all line ups and rectifiers for overtemp indications	COMP	06/22/09	PC	0	06/21/09		AMVS EPCOT Monorail Beam	BEAM	Replaced 22475 transmitter and beam was 10-8
42	26062232	06/22/09	NS Monorail Shop	EPCOT BEAM BENCH REPAIR AND TEST MAPO TRANSMITTERS	INPRG	06/22/09	PC	1	06/22/09		AMVS EPCOT Monorail Beam	BEAM	Found all building fans operational, also pcm cabinet fans which were wired 10-8
43	26301135	07/02/09	NS Monorail Shop	EPCOT PYLON 386 TRANSMITTER AND POWER SUPPLY 10/7	COMP	07/02/09	UCH	4	07/02/09		AMVS EPCOT Monorail Beam	BEAM	
44	26301798	07/02/09	NS Monorail Shop	EPCOT LINE UP ONE CONTACTOR 1 10/7	INPRG	07/02/09	UCH	3	07/02/09		AMVS EPCOT Monorail Beam	BEAM	REPLACED TRANSMITTER AND POWER SUPPLY SYSTEM 10/8 REPLACED TYPE 82 RECLOSURE 10/8