

DCA09FR008
Lake Buena Vista, Florida
July 5, 2009

Switch Panel Event Log
Post Accident Testing

Time	_TimeUTC	_TimeMsecs	_Source	_ConditionName	Message	_EventTime
7/5/09 8:29 AM	7/5/09 12:29 PM	562	Rectifier 2 24V Battery Backup Unit Status	Digital	Rectifier 2 24V Battery Backup Unit Fault	7/5/2/009
7/5/09 8:29 AM	7/5/09 12:29 PM	593	Rectifier 2 24V Battery Status	Digital	Rectifier 2 24V Battery Fault	7/5/2/009
7/5/09 8:34 AM	7/5/09 12:34 PM	531	Rectifier 2 24V Battery Backup Unit Status	Digital	Rectifier 2 24V Battery Return to Normal	7/5/2/009
7/5/09 8:34 AM	7/5/09 12:34 PM	531	Rectifier 2 24V Battery Status	Digital	Rectifier 2 24V Battery Return to Normal	7/5/2/009
7/5/09 8:10 PM	7/5/09 9:10 PM	765	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Return to Normal	7/5/2/009
7/5/09 8:10 PM	7/5/09 9:10 PM	796	SWB 9 Power Removed Externally	Digital	SWB 9 Power Removed Externally Return to Normal	7/5/2/009
7/5/09 8:49 PM	7/5/09 9:49 PM	109	SWB 8 To Spur Fail	Digital	SWB 8 To Spur Fail	7/5/2/009
7/5/09 8:50 PM	7/5/09 9:50 PM	93	SWB 8 To Spur Fail	Digital	SWB 8 To Spur Fail Return to Normal	7/5/2/009
7/5/09 8:50 PM	7/5/09 9:50 PM	202	M: SWB 8 To Spur Fail	Digital	M: SWB 8 To Spur Fail	7/5/2/009
7/5/09 8:50 PM	7/5/09 9:50 PM	93	M: SWB 8 To Spur Fail	Digital	M: SWB 8 To Spur Fail Return to Normal	7/5/2/009
7/5/09 8:59 PM	7/5/09 9:59 PM	109	SWB 9 To Spur Fail	Digital	SWB 9 To Spur Fail	7/5/2/009
7/5/09 8:00 PM	7/5/09 10:00 PM	93	SWB 9 To Spur Fail	Digital	SWB 9 To Spur Fail Return to Normal	7/5/2/009
7/5/09 8:04 PM	7/5/09 10:04 PM	93	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Active	7/5/2/009
7/5/09 8:05 PM	7/5/09 10:05 PM	93	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Return to Normal	7/5/2/009
7/5/09 8:05 PM	7/5/09 10:05 PM	109	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Return to Normal	7/5/2/009
7/5/09 8:17 PM	7/5/09 10:17 PM	234	Remote E-Stop Released Too Early	Digital	Remote E-Stop Released Too Early	7/5/2/009
7/5/09 8:17 PM	7/5/09 10:17 PM	234	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Return to Normal	7/5/2/009
7/5/09 8:18 PM	7/5/09 10:18 PM	171	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Active	7/5/2/009
7/5/09 8:18 PM	7/5/09 10:18 PM	171	Roundhouse Switchbeam 8&9 Kill Button	Digital	Roundhouse Switchbeam 8&9 Kill Return to Normal	7/5/2/009
7/5/09 8:21 PM	7/5/09 10:21 PM	187	Remote E-Stop Released Too Early	Digital	Remote E-Stop Released Too Early Return to Normal	7/5/2/009